

Assessment Summary Report

Corporate Client:	AAMI	Claim No:	M075962703
Work Location:	Barry James Smash Repairs	State:	
Claim Decision:	Accept	Repairs Authorised:	Yes
		Customer Type:	Our Insured

ASSESSMENT DETAILS

Vehicle:	2012 MAZDA CX-5 GRAND TOURER (4X4) 4D WAGON 6 SP AUTOMATIC, 4 CYL DIESEL TURBO,		
Booking:	7 December 2022 08:45	Customer:	HELEN MILLER
Process Type:	VALET	Cover:	Comprehensive Motor Insurance
Loss Cause:	Accidental Damage whilst parked	Incident Date:	Tuesday, 18 October, 2022 11:30
Assessor:	Alex Borg	Assessed Date/time:	7 December 2022 08:45

VEHICLE DETAILS

Vehicle Style:	standard	Vehicle PAV:	
Registration:	YXE158	Condition:	Above Average
Cylinders:		Transmission:	
Sum Insured Vehicle Value Amount Covered:	\$19,700.00	VIN:	JM0KE102100107713
Colour:	Grey	Modifications:	Nil
Paint Type:	metallic	Accessories:	Nil
Odometer:	143008		
Manuf Mth/yr :	2012		
Reported Damage:	E_CentreRear:medium		
Repairer:	Barry James Smash Repairs - 03 5329 2222		

IMPACT DAMAGE:

OLD DAMAGE: